

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL002007	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 12/30/2014
NAME OF PROVIDER OR SUPPLIER A NEW OUTLOOK OF TAYLORSVILLE		STREET ADDRESS, CITY, STATE, ZIP CODE 360 WOOD ROAD TAYLORSVILLE, NC 28681		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 000	Initial Comments Report of Complaint Survey by Dennis Harrell on 12-18-2014 and 12-30-2014. The complaint was a report of a fire and allegations that the staff is not properly trained on procedures to follow during a fire. Records indicate that this facility was first submitted or licensed in 6-1-1974, for a capacity of 34 Beds. Based on this information, the facility was surveyed using the 1971 Minimum and Desired Standards and Regulations for Homes for the Aged and Infirm, the 1967 North Carolina State Building Code Section 407 - Group D Institutional and the applicable portions of the 2005 Rules for Adult Care Homes of Seven or More Beds. The Complaint was unsubstantiated.	C 000		
C 166	Housekeeping-Maintained Free of Hazards SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0306 HOUSEKEEPING AND FURNISHINGS (a) Adult care homes shall: (5) be maintained in an uncluttered, clean and orderly manner, free of all obstructions and hazards; (e) This Rule shall apply to new and existing facilities. This Rule is not met as evidenced by: Based on observation, the bedroom where the fire occurred was not unsuitable for habitation. Findings include: a. The window to the exterior was damaged and had been partially removed. b. There was scorching and heavy smoke	C 166		

Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL002007	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 12/30/2014
NAME OF PROVIDER OR SUPPLIER A NEW OUTLOOK OF TAYLORSVILLE		STREET ADDRESS, CITY, STATE, ZIP CODE 360 WOOD ROAD TAYLORSVILLE, NC 28681		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 166	Continued From page 1 damage in the room. c. The ceiling radiation dampers in the supply and return ducts had activated and closed. This room must not be used as a bedroom until the window is replaced, the damage repaired and the raditaion dampers are reset using manufacturer's approved fuse links.	C 166		